

Endwall Column attachment located between Purlins at Slope

SHT. NO.
EF09102

DATE
Dec '12

REV. NO.
01

Notes;

- 1.) See AC00916 / AC00920 for Jamb/Support Column attachment when located at same Purlin space (or adjacent Purlin space) as Endwall Column.
- 2.) Bridge Channel may span multiple Purlin spaces when required.
- 3.) Wind Edge Strip Purlins, when required, do not attach to Bridge Channel.
- 4.) Purlins and Purlin Strut extends past Bridge Channel flange when "Optional" Overhang or Facade is required at endwall.

